

Test Report No.: SZXEC25000628307 Date: Mar 13, 2025 Page 1 of 4

Client Name: SHENZHEN CITY DAXING ADHESIVES CO LTD.

Client Address: SALCOMP AVENUE, BAO'AN DISTRICT, STREET NEWBRIDGE FURONG INDUSTRIAL

ZONE OF SHENZHEN CITY PLANT NO. 73, BUILDING C

Sample Name: Cement Model No.: YB-1688

Client Ref. Information: Attached Name: Halogen-free xanthan gum

1603HFR-G, 1603HFR-HS, 1603HFR-1 SR-9000、2908、

1663M DX-1663M \ DX-1603

Supplier: DAEHEUNG

The above sample(s) and information were provided by the client.

SGS Job No.: SZP25-009478 Sample Receiving Date: Mar 06, 2025

Testing Period: Mar 06, 2025 ~ Mar 12, 2025

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

Test Requirement	Conclusion
Halogen	See Results

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

lina

Tina Fan

Approved Signatory





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck-Rosus.com

Room 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 3 & Room 301-501, Plant 3, Janghao (Banfan) Industrial Plant Ana, No. 403, Jihua Rood, Sanfan Community, Banfan Sinet, Longsang Districk, Shenzhen, Guanplong, China 18129 www.sepsgroup.com.cn 中国・广东・深圳市龙岗区城田街道坂田社区吉华路430号江薫(坂田)工业厂区厂房4号101-901、2号101、3号301-501 南编:518129 (166-755) 25328888 sgs.china@sgs.com



Test Report No.: SZXEC25000628307 **Date**: Mar 13, 2025 Page 2 of 4

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A2	SZX25-0006283-0001.C002	Yellow paste

Remarks:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A2
Fluorine(F)	mg/kg	20	ND
Chlorine(CI)	mg/kg	50	136
Bromine(Br)	mg/kg	50	ND
Iodine(I)	mg/kg	50	ND

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.


Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck-Rogas.com

Roum 101-901, Plant 48 Room 101, Plant 28 Room 101, Plant 28 Room 101-901, Plant 3, Room 301-501, Plant 3, Rong 301-501, Plant 3, Room 3



Test Report ATTACHMENTS

Halogen Testing Flow Chart





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck-Rogas.com

Roum 101-901, Plant 4 & Roum 101, Plant 2 & Roum 101, Plant 2 & Roum 101, Plant 3 & Roum 101-901, Plant 3, Ranghao (Ranfan) Industrial Plant Area, No. 400, Jihua Road, Barifan Community, Bantian Street, Longgang Districk, Shenzhen, Guanplong, China 1818/29 wwww.sgs-ggroup.com.cn 中国 - 广东 - 深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田) 工业厂区厂房4号101—901、2号101、3号301—501 单编:518129 (166-755) 25328888 sgs.china@sgs.com



Test Report No.: SZXEC25000628307 **Date**: Mar 13, 2025 Page 4 of 4

Sample Photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction form exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior writine approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com